Date:

Tuesday, 12/08/2008 9:02:02 AM

User:

Melanie Fauteux

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 41158

Estimate Number

: 13345

P.O. Number

This Issue

Prsht Rev.

First Issue

: 12/08/2008

: NC

: 11 : 40957

Type

S.O. No. :

: LARGE FAB ASSY

Part Number

Drawing Name

: D3763041

: END FITTING ASS'Y

Drawing Number

: D3763 REVB

Project Number Drawing Revision : N/A : B

Material

Due Date

: 12/08/2008

Qty:

2 Um:

Each

Written By

Previous Run

Checked & Approved By Comment

: Est Rev:A 08-05-20 new issue DD verified by:ec

Est Rev:B 08-07-18 revB as per dwg DD verified by:EC Est Rev:C 08-08-11 add chemical coat and qc3 DD verified

by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

2.0

D37631

End Fitting




Comment: Qty.:

1.0000 Each(s)/Unit

Total:

2.0000 Each(s)



batch: 4/0 991



3.0


D37633

Tube




Comment: Qty.:

Total:



2.0000 Each(s)



4.0

LARGE FABRICATION RESOURCE



Comment: LARGE FABRICATION RESOURCE 1

1-make a 0.063" chamfer on D3763-1 fitting before ass'y

2-assemble as per dwg D3763 using locating pin DT *******ensure locating pin is in 0.221" hole*

3-weld as per dwg D3763 QSI004

Alum. rod Batch: M 104



Date: Tuesday, 12/08/2008 9:02:02 AM User: Melanie Fauteux **Process Sheet** Drawing Name: END FITTING ASS'Y Customer: CU-DAR001 Dart Helicopters Services Job Number: 41158 Part Number: D3763041 Job Number: Seq. #: **Description: Machine Or Operation:** VISUAL WELDING INSPECTION 5.0 QC9 Comment: VISUAL WELDING INSPECTION (D) QC5 6.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING1 HAND FINISHING RESOURCE #1 7.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERS 8.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify wiith Dart part # using a fine point permanent marker and Stock Location: 6-A-FINAL INSPECTION/W/O RELEASE 10.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

